

CITY OF SAINT PAUL, MN

DEPARTMENT OF SAFETY AND INSPECTIONS

Steve Magner, Manager of Code Enforcement Vicki Sheffer, Truth-in-Sale of Housing Manager

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

Phone: 651-266-8989 Fax: 651-266-1919 Web: <u>www.stpaul.gov/dsi</u>

Truth-in-Sale of Housing Report

This is a visual disclosure report based on the current City of Saint Paul Truth-in-Sale of Housing Evaluator Guidelines and is valid for one year from the date of issuance and for the owner named.

Property Address: 2175 LINCOLN AVE

Date of Evaluation: Jan 11, 2023 Date of Expiration: Jan 11, 2024

This report is intended to provide basic information to the home buyer and seller prior to the time of sale.

This report WILL NOT be used to enforce the requirements of the Legislative Code; however, it will be used to determine if there is compliance with the requirements for sale within the City of Saint Paul, MN.



MAJOR NOTIFICATIONS AND WARNINGS

For questions on these items, call the City's Information and Complaint Line at 651-266-8989

- Residential Type: Single Family Dwelling
- Smoke Detectors:
 - Smoke Detector Present: Y
 - Smoke Detector Properly Located: Y
 - Smoke Detector Hard Wired (required in Single Family Homes): Y
 - Smoke Detector Comments:
- Open Permits:

This property has the following open permits:

B - 22 113266 - REROOF (SHINGLE WITH TEAR OFF) - Active/Issued

HAZARDOUS

Enclosed Porches and Other Roc

Electrical outlets and fixtures

Exterior Space

- Outlets, fixtures and service entrance
- Sleeping Room(s)
 - Electrical outlets and fixtures

BELOW MINIMUM

Basement/Cellar

· Stairs and Handrails

Enclosed Porches and Other Roc

Window and door condition

Exterior Space

Windows (frames/storms/screens)

Hallways, Stairs and Entries

• Stairs and handrails to upper floors

Living and Dining Room(s)

• Window and door condition

Plumbing System

• Gas piping (all floors)

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must <u>specify the room</u> to which a Comment is related)			
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

CITY OF SAINT PAUL TRUTH-IN-SALE OF HOUSING REPORT

Μ

Υ

M

Address: 2175 LINCOLN AVE Date of Evaluation: Jan 11, 2023

Zoning District: R3 Present Occupancy:

Number of Units Evaluated: Single Family

Dwelling

Basement/Cellar

1. Stairs and Handrails В

2. Basement/Cellar Floor M

3. Foundation

4. Evidence of Dampness or

Staining 5. First Floor, Floor System

6. Beams and Columns M

Electrical Services

7a. Number of Electrical Services 1

7b. Amps 100

7c. Volts 120-240

Basement Only

8. Electrical service M installation/grounding

9. Electrical wiring, outlets and M

fixtures

Plumbing System

10. Floor drain(s) (basement) M

11. Waste and vent piping (all M

floors)

12. Water piping (all floors)

M

13. Gas piping (all floors) В

14. Water heater(s), installation M

15. Water heater(s), venting NA

16. Plumbing fixtures

(basement)

Heating System(s)

The Evaluator is not required to operate the heating plant(s) except during the heating season, between October 15 and April 15.

File Number: File#: 23-004588

Owner: Brian A Dawood/Cari Dawood Client Name: Cari and Brian Dawood

Client Contact: 651-233-3456

Evaluator Name: Alan Copia Cornerstone Inspec

Evaluator Contact: Work: 612-824-2000

alanjcopia@gmail.com

1. B - Headroom less than 6 feet 8 inches.B - High riser heights, handrail is higher than 38" above the

treads.

2. C - 3, 4, 5, 6 Finished surfaces, stored items.

Limited views throughout.

4. C - Evidence of previous dampness or staining

(typical).

10. C - could not remove cover due to stored

items.

12. B - Missing backflow preventer/s at threaded

faucets.

13. B - No sediment trap visible at the dryer gas line.C - The gas line was not visible at the stove.

14. C - Older appliance.

2175 LINCOLN AVE Evaluator: Alan Copia Cornerstone Inspections Inc

M

Page # 3

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related) B: Below Minimum C: See Comments M: Meets Minimum Y: Yes N: No NV: Not Visible NA: Not Applicable

17a. Number of Heating 1 **Systems** 17b. Type Forced Air 17c. Fuel Gas 18. Installation and visible M condition 19. Viewed in operation Υ (required in heating season) 20. Combustion venting Μ 21a. Additional heating unit(s): NA 21b. Additional heating unit(s): NA Fuel 21c. Installation and visible NA condition 21d. Viewed in operation NA 21e. Combustion venting NA Kitchen 22. Walls and ceiling M 23. Floor condition and ceiling M height 24. Evidence of dampness or Ν staining 25. Electrical outlets and M fixtures 26. Plumbing fixtures M 27. Water flow M 28. Window size/openable Μ area/mechanical exhaust 29. Condition of Μ doors/windows/mechanical exhaust Living and Dining Room(s) 30. Walls and ceiling M 31. Floor condition and ceiling M height 32. Evidence of dampness or Ν staining 33. Electrical outlets and M fixtures 34. Window size and openable M area 35. Window and door condition В 35. B - Some of the double hung windows are inoperative (frozen due to weather conditions?). Hallways, Stairs and Entries 36. Walls, ceilings, floors M 37. Evidence of dampness or Ν staining 38. Stairs and handrails to В 38. B - High risers, low headroom.B - Handrail(s) upper floors not continuous or lacks return.

2175 LINCOLN AVE

Jan 11, 2023

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must <u>specify the room</u> to which a Comment is related)					
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum		
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable		
39. Electrical outlets and M					
fixtures					

1: 162		INV: NOT VISIBLE	NA: NOt Applicable
39. Electrical outlets and fixtures	M		
40. Window and door condit	ions M		
Smoke Detectors			
41a. Present	Y		
41b. Properly Located 41c. Hard-Wire	Y Y		
Bathroom(s)	'		
42. Walls and ceiling	М		
43. Floor condition and ceili			
height	ng M		
44. Evidence of dampness of staining	r N		
45. Electrical outlets and fixtures	М		
46. Plumbing fixtures	M		
47. Water flow	M		
48. Windows size/openable area/mechnical exhaust	M		
49. Condition of windows/doors/mechanical exhaust	М		
Sleeping Room(s)			
50. Walls and ceilings	M		
51. Floor condition, area and ceiling height	d M		
52. Evidence of dampness of staining	r N		
53. Electrical outlets and fixtures	Н	53. H - Ungrounded 3 pron	g outlets.
54. Window size and openal area 55. Window and door condit			
Enclosed Porches and Othe			
56. Walls, ceiling and floor condition	М		
57. Evidence of dampness of staining			
58. Electrical outlets and fixtures	. H	58. H - The GFCI outlets on trip when tedted.	·
59. Window and door condit	ion B	59. B - fogged glass at the	front porch windows.
Attic Space			
60. Roof boards and rafters	M	60. C - Finished surfaces, a visible. We could not detern depth due to finished surface.	nine insulation type or
61. Evidence of dampness of staining	r Y	61. C - Evidence of previou	
62. Electrical wiring/outlets/fixtures	М		
63. Ventilation	Υ		

2175 LINCOLN AVE
Evaluator: Alan Copia Cornerstone
Inspections Inc

Jan 11, 2023

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related) H: Hazardous Condition B: Below Minimum C: See Comments M: Meets Minimum N: No NV: Not Visible NA: Not Applicable Y: Yes

Exterior Space		
64. Foundation	M	
65. Basement/cellar windows	М	
66. Drainage (grade)	NV	66. C - Snow covered, could not evaluate.
67. Exterior walls	М	
68. Doors (frames/storms/screens)	M	
69. Windows (frames/storms/screens)	В	69. B - Some windows appear to be fogged, lost seal at thermopanes.
70. Open porches, stairways and deck(s)	M	
71. Cornice and trim(s)	M	
72. Roof structure and covering	NV	72. C - Snow covered, could not evaluate.
73. Gutters and downspouts	M	
74. Chimney(s)	NV	
75. Outlets, fixtures and service entrance	Н	75. H - The GFCI outlet above the rear stoop did not trip when tested.
Garage(s)/Accessory Structure(s	•	
76. Roof structure and covering	NV	76. C - Snow covered, could not evaluate.
77. Wall structure and covering	M	77.
78. Slab condition	M	78. C - Cracked slab, stored items, limited views.
79. Garage door(s)	М	
80. Garage opener(s)	Υ	
81. Electrical wiring, outlets and fixtures	M	
Fireplace/Woodstove		
82. Number of Units	1	
83. Dampers installed	Υ	
84. Installation	M	
85. Condition	M	
Insulation		
86a. Attic Insulation: Present	NV	
86b. Attic Insulation: Type	NV	
86c. Attic Insulation: Depth	NV	
87a. Foundation Insulation: Present	NV	
87b. Foundation Insulation: Type	NV	
87c. Foundation Insulation: Depth	NV	
88a. Knee Wall Insulation: Present 88b. Knee Wall Insulation: Type	NV NV	
88c. Knee Wall Insulation: Depth	NV	
ooc. Knee wan insulation. Depth	INV	

2175 LINCOLN AVE Jan 11, 2023 Evaluator: Alan Copia Cornerstone

	Report Rating Key (Where there are multiple rooms to a category, the Evaluator must <u>specify the room</u> to which a Comment is related			n to which a Comment is related)
	H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Ī	Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

NV

89a. Rim Joist Insulation:

Present

89b. Rim Joist Insulation: Type NV89c. Rim Joist Insulation: Depth NV

General

90. Carbon Monoxide Alarm Μ

General Comments C - The hardwired smoke alarm is located near Μ

the basement bedroom.

2175 LINCOLN AVE Jan 11, 2023 Evaluator: Alan Copia Cornerstone

Inspections Inc

LEGAL NOTICES:

Chapter 189 of the Saint Paul Legislative Code requires all single family, duplex, condo, townhouse and co-op homes for sale in the city to have a Truth-in-Sale of Housing disclosure report prepared and available to prospective buyers. A Truth-in-Sale of Housing disclosure report must be done for Contract-For-Deed sales.

A Truth-in-Sale of Housing (TISH) Disclosure Report in the City of Saint Paul is intended to provide basic information to the home buyer and seller prior to the time of sale. Failure to obtain a Truth-in-Sale of Housing disclosure report or failure to make that disclosure report available to prospective buyers, is a violation of law and is punishable as a misdemeanor carrying up to 90 days in jail and/or a \$1,000.00 fine.

A valid Truth-in-Sale of Housing disclosure report must be conspicuously displayed at the premises for all prospective buyers. TISH disclosure reports are also available online: https://online.stpaul. gov/web/portal/public-search

- This report WILL NOT be used to enforce the requirements of the Legislative Code; however, this evaluation form will be used to determine if there is compliance with the requirements for a hardwired smoke detectors.
- This TISH report is based on the current Truth-in-Sale of Housing Evaluator Guidelines and is based upon different standards than the lender, Federal Housing Administration (FHA) or Veterans Administration (VA).
- This TISH is not warranted, by the City of Saint Paul nor by the evaluator for the condition of the building component, nor of the accuracy of this report.
- This TISH report covers only the items listed on the form and only those items visible at the time of the evaluation.
- The Evaluator is not required to operate the heating plant (except during the heating season), use a ladder to observe the condition of the roofing, disassemble items or evaluate inaccessible areas.
- This TISH report is valid for one year from the date of issue and only for the owner named on this
- If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at (651) 266-9008.
- Automatic garage doors should reverse upon striking an object. If it does not reverse, it poses a serious hazard and should be repaired or replaced immediately.
- All single family residences in Saint Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, (651)228-6230. (Saint Paul Legislative Code, Chapter 58.)
- Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, and (651)266-6234.
- A house built before 1950 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, (651)292-6525.
- Neither the City of Saint Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.

Questions regarding this report should be directed to the evaluator. If you desire a reinspection and amended report, please contact your evaluator. They will perform a reinspection and file an amended report with the City of Saint Paul. The TISH evaluator may charge for this reinspection. Complaints regarding this report should be directed to Department of Safety and Inspections, Truth-in-Sale of Housing Program, Phone 651-266-8989.

2175 LINCOLN AVE Jan 11, 2023 Evaluator: Alan Copia Cornerstone

Inspections Inc

Evaluator Statement:

I hereby certify I prepared this report in compliance with the Saint Paul Evaluator Guidelines, City of Saint Paul City Ordinance 189 and all other applicable policies and procedures of the Truth-in_Sale of Housing Board. I have utilized reasonable and ordinary care and diligence and I have noted all conditions found that do not conform to the minimum standards of maintenance. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrent future useful life of any house component or fixture. I have included all required information pages with this report. Evaluator Name: Alan Copia Cornerstone Inspections Inc

Phone: Work: 612-824-2000 Evaluation Date: Jan 11, 2023

2175 LINCOLN AVE Jan 11, 2023 Evaluator: Alan Copia Cornerstone

Inspections Inc