NOTICE - Read Entire Report Carefully. This is not a Buyer's Inspection!

Address: 410 5TH AVE SE Minneapolis, MN



**Business/Relationship:** 

City of Minneapolis

Truth in Sale of Housing

Owner Address: 410 5TH AVE SE

Minneapolis, MN 55414

# I declare to the best of my knowledge the following information: This property has had environmental testing, removal, or remediation of environmental contamination by the United States Environmental Protection Agency, Minnesota Pollution Control Agency, other governmental agency, or under the direction of such agency: Yes / No If yes, the seller shall provide the testing, removal, or remediation results to the buyer. Water Damage to Property: flood damage sewer backup water seepage Please Describe: Age of Roof: \_\_\_\_\_ Condition of Roof: Poor Fair Good Excellent Currently Leaking: Yes / No Patched: Yes / No Signature of Owner: (Report Not Valid Without Signature) Date:

\*\*\*\*\*\*\* SEE ATTACHED PAGES FOR IMPORTANT CONSUMER INFORMATION \*\*\*\*\*\*\*

#### THERE ARE REQUIRED REPAIR/REPLACE ITEMS NOTED IN THIS REPORT.

Observed Number of Units: 2 City Reference as: 2

Building Type: Duplex/Multiplex Present Occupancy: Non-conforming due to lot size

Zoning: R2B - Two Family District(`99)

Note: The occupancy is indicated as Nonconforming, the owner shall provide the buyer, prior to closing, settlement, or transfer of

ownership, a written and signed verification as to the zoning status by the City Zoning Administrator.

**Housing Orders:** No

Condemnation Status: NA Reason: NA

- 1. This report offers a limited overview of the building components and fixtures and is not technically extensive. Prospective buyers may want to seek additional opinions from various experts in the inspections field prior to purchase. This report is not a warranty or guarantee, expressed or implied, by the City of Minneapolis or by the evaluator or of any building component or fixture. Further, the buyer may want to seek additional information regarding any open permits. For 1st time condominium units, this report includes only those items located within the residential units. The Professional Opinion covers those items in the common areas of the building.
- 2. The buyer must repair all items marked Repair/Replace, unless the seller agrees to do the repairs. The seller is not required to complete the RR's if the property does not sell. All required Repair/Replace items are enforceable by Minneapolis Ordinance Chapter 248 and/or 250. All other items will not be used by the Inspections Division as a basis for enforcing Minneapolis ordinances.
- 3. The ordinance requires that no person shall exhibit or show a dwelling for sale without first having obtained an official Evaluation Report and places the responsibility on the seller or agent to make sure that this report (and in the case of 1st time condo conversions, the Professional Opinion,) is publicly displayed on the premises at all times when the house is shown to prospective buyers. Also, the seller or agent must give a copy of this report (and Professional Opinion for 1st time condo conversions) to the buyer prior to the signing of a Purchase Agreement, or as otherwise required in Minneapolis Ordinance Chapter 248 and/or 250.
- 4. This report covers only those items listed on the form. The evaluator is not required to ignite the heating plant, use a ladder to observe the condition of the roofing, evaluate inaccessible or concealed areas or disassemble items. This report does not address formaldehyde, lead paint, any airborne gasses (including radon), asbestos, wood stoves, fireplaces or air conditioners. Gas inserts in fireplaces WILL be evaluated.
- 5. This report is not an FHA, VA or Section 8 inspection. This report is not a code compliance inspection. It is not an appraisal. This report may be based upon different standards than the lender, FHA or VA.
- 6. The seller is required to provide the disclosure information in the box above. If this is not filled out, buyers are advised to request the seller to do so.
- 7. This report is valid for two years from the date of issue and <u>only for the owner</u> named on the report. It is required for all single-family homes, duplexes, townhouses or 1<sup>st</sup> time condominium conversions offered for sale.
- 8. **Any questions** regarding this report should be directed to the evaluator whose name and phone number appear below. **Any complaints** regarding this report should be directed to Truth in Housing at (612) 673-5840, Minneapolis Inspections Division, 250 South 4<sup>th</sup> Street #300, Minneapolis, MN 55415.

I hereby certify that this report is made in compliance with the Minneapolis Code of Ordinances, Chapter 248, and that I utilized care and diligence reasonable and ordinary for one meeting the Certification Standards. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrant future useful life of any house component or fixture. I have included all required information pages with this report.

Evaluator Name: Alan Copia Phone: 612-824-2000 Evaluation Date: 11/17/2014

Signature: Alan Copia Evaluation #: 20145983

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification
Required

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

#### Unit 1

#### Basement (410 5th Ave SE)

- 1. Basement Stairs/Railings
  - M, Meets Minimum Requirements
- 2. Basement Floors
  - C, Other Comment: C, Views of the floor are limited by stored items.
- 3. Foundation Walls
  - B, Below Minimum Requirements: B, Spalling in areas, missing mortar
- 4. Evidence of Dampness or Staining
  - C, Evidence of past dampness and/or staining.
- First Floor, Floor System
  - M, Meets Minimum Requirements
- 6. Columns & Beams
  - B, Adjustable posts not welded/peened/anchored.
- 7. Basement Sleeping Rooms
  - C, There are no basement bedrooms.
- 8. Basement Plumbing Fixtures
  - M, Meets Minimum Requirements
- 9. Sump Pumps
  - C, No sump pump present.
- 10. Smoke Detectors / CO Detectors
  - M, Meets Minimum Requirements
- 11. Basement Electrical Outlets/Fixtures
  - M, Meets Minimum Requirements

#### **Electric**

**Amps:**100

Volts:115/230

12. Electrical service installation

RRE, Electric shock possible by direct contact, missing breaker in panel. - Multiple breakers missing

13. Separate 20-amp Kitchen Circuit indexed at Service Panel

M, Meets Minimum Requirements

14. Separate 20-amp Laundry Circuit indexed at Service Panel

M, Meets Minimum Requirements

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 2 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

### **Plumbing**

- 15. Floor Drains
  - C, Other Comment: C, none visible
- 16. Drain, Waste & Vent Piping
  - B, Improper waste connections (rubber connector is incorrect). Only steel banded is correct.
  - C, Other Comment: C, corrosion at waste piping.
- 17. Water Supply Piping
  - M, Meets Minimum Requirements
- 18. Gas Piping
  - M, Meets Minimum Requirements
- 19. Copper Water Line Visible on the Street Side of Water Meter
  - M, Meets Minimum Requirements

#### Water heater

- 20. Water Heater & Installation
  - M, Meets Minimum Requirements
- 21. Water Heater Venting
  - M, Meets Minimum Requirements

#### Heating (410 5th Side)

**HeatingFuel:**Gas **HeatingType:**boiler

- 22. Heating Plant Viewed in Operation
  - M, Meets Minimum Requirements
- 23. Heating Plant & Installation

RRP, Missing or improper double check valve with intermediate atmospheric vent (DCVIAV or backflow preventer) on water supply to boiler. Plumbing permit required.

24. Heating Plant Combustion Venting

RRP, Rust holes/open joint(s). Installation of new venting requires a mechanical permit by licensed Minneapolis contractor.

25. Incinerator / Abandoned Oil Tanks / Misc Gas Fixtures

NA, Not Applicable/Does Not Apply

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 3 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

## Laundry

- 26. Gas Piping
  - B, Below Minimum Requirements: B, Missing sediment trap.
- 27. Dryer Venting
  - M, Meets Minimum Requirements
- 28. Plumbing Fixtures
  - B, Below Minimum Requirements: B, laundry tub is not properly vented.

#### Kitchen

- 29. Walls and Ceiling Components
  - M, Meets Minimum Requirements
- 30. Evidence of Dampness or Staining
  - M, Meets Minimum Requirements
- 31. Floor Condition
  - M, Meets Minimum Requirements
- 32. Window Size & Openable Area
  - M, Meets Minimum Requirements
- 33. Window & Door Condition/Mechanical Venting
  - C, Other Comment: C, windows are plastic covered, could not evaluate.
- 34. Electrical Outlets/Fixtures
  - M, Meets Minimum Requirements
- 35. Plumbing Fixtures
  - B, Unvented kitchen sink.
- 36. Water Flow
  - M, Meets Minimum Requirements
- 37. Gas Piping
  - B, Below Minimum Requirements: B, lacks sediment trap.

**Evaluator Name**: Alan Copia **Evaluation Date**: 11/17/2014 Page 4 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

#### Required

## **Dining Room/Living Room**

- 38. Walls and Ceiling Components
  - M, Meets Minimum Requirements
- 39. Evidence of Dampness or Staining
  - M, Meets Minimum Requirements
- 40. Floor Area & Ceiling Height
  - M, Meets Minimum Requirements
- 41. Floor Condition
  - M, Meets Minimum Requirements
- 42. Window Size & Openable Area
  - M, Meets Minimum Requirements
- 43. Window & Door Condition
  - C, Other Comment: C, windows are plastic covered, could not evaluate.
- 44. Electrical Outlets/Fixtures
  - C, Limited view due to stored items or furnishings.

### Bathroom (2nd fl)

- 45. Walls & Ceiling Components
  - M, Meets Minimum Requirements
- 46. Evidence of Dampness or Staining
  - M, Meets Minimum Requirements
- 47. Floor Condition
  - M, Meets Minimum Requirements
- 48. Window Size & Openable Area/Mechanical Vent
  - M, Meets Minimum Requirements
- 49. Window & Door Condition
  - M, Meets Minimum Requirements
- 50. Electrical Outlets & Fixtures
  - M, Meets Minimum Requirements
- 51. Plumbing Fixtures
  - B, Below Minimum Requirements: B, fixtures lack required clearences
- 52. Water Flow
  - M, Meets Minimum Requirements

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 5 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

## Hallways/Stairwells

53. Walls and Ceiling Components

M, Meets Minimum Requirements

54. Evidence of Dampness or Staining

M, Meets Minimum Requirements

55. Floor Condition

M, Meets Minimum Requirements

56. Window & Door Condition

M, Meets Minimum Requirements

57. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

58. Stairs and Railings

B, Below Minimum Requirements: - B, Low guardrail, less than 36".

59. Smoke Detectors /CO Detectors

M, Meets Minimum Requirements

### Bedroom (2nd fl front)

60. Walls and Ceiling Components

M, Meets Minimum Requirements

61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

63. Floor Condition

M, Meets Minimum Requirements

64. Window Size & Openable Area

M, Meets Minimum Requirements

65. Window & Door Condition

M, Meets Minimum Requirements

66. Electrical Outlets/Fixtures

C, Limited view due to stored items.

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 6 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

## Bedroom (2nd fl mid)

60. Walls and Ceiling Components

M, Meets Minimum Requirements

61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

63. Floor Condition

M, Meets Minimum Requirements

64. Window Size & Openable Area

M, Meets Minimum Requirements

65. Window & Door Condition

M, Meets Minimum Requirements

66. Electrical Outlets/Fixtures

C, Limited view due to stored items.

### Bedroom (2nd fl rear)

60. Walls and Ceiling Components

M, Meets Minimum Requirements

61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

63. Floor Condition

M, Meets Minimum Requirements

64. Window Size & Openable Area

M, Meets Minimum Requirements

65. Window & Door Condition

M, Meets Minimum Requirements

66. Electrical Outlets/Fixtures

C, Limited view due to stored items.

#### Porch/Sunroom/Other

Not Applicable

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 7 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification RRP:=Repair/Replace, Permit/City Inspector Required LIC:=Safety Check, Licensed Contractor Required

Required

## **Attic Space**

InsulationType: Not Visible

InsulationDepth: 3-6

72. Roof Boards & Rafters / Ventilation

RRE, Repair/Replace: - RRE, access to attic is locked, could not view

73. Evidence of Dampness or Staining

M, Meets Minimum Requirements

74. Electrical Outlets & Fixtures

M, Meets Minimum Requirements

75. Mechanical Venting

NA, Not Applicable/Does Not Apply

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 8 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

#### **Exterior**

- 76. Foundation
  - M, Meets Minimum Requirements
- 77. Basement Windows
  - B, Cracked window.
  - B, Deteriorated basement window(s).
  - B, Boarded up window(s).
- 78. Drainage (Grade) / Rainleaders
  - C, Snow covered in areas, can't fully view.
- 79. Exterior Walls
  - B, Weathered/damaged siding. missing metal siding components.
- 80. Doors (frames/storms/screens/deadbolt locks)
  - B, Damaged/deteriorated storm door(s).
- 81. Windows (frames/storms/screens)
  - M, Meets Minimum Requirements
- 82. Stoops
  - SC, Suggested Correction: SC, the rear bump outs on both sides are settled, deteriorated.
- 83. Cornice & Trim
  - M, Meets Minimum Requirements
- 84. Roof Covering & Flashing
  - C, Roof is snow/frost covered and not fully visible. Not evaluated.
  - C, Branches in contact with roof.
- 85. Chimney
  - SC, Suggested Correction: SC, missing bricks, loose mortar. Boiler flues lack rain caps.
- 86. Electrical Outlets/Fixtures
  - M, Meets Minimum Requirements
- 87. Exterior Plumbing-Backflow Prevention
  - M, Meets Minimum Requirements
- 88. Two-Family Dwelling Egress
  - M, Meets Minimum Requirements

**Evaluator Name**: Alan Copia **Evaluation Date**: 11/17/2014 Page 9 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

#### Required

### **Open/Unheated Porch**

- 89. Floors
  - C, Floor out of level.
  - C, Stored items prevent full evaluation.
- 90. Walls
  - M, Meets Minimum Requirements
- 91. Roof/Ceiling
  - C, Other Comment: snow covered, not visible.
- 92. Doors/Screens/Windows
  - M, Meets Minimum Requirements
- 93. Electrical Outlets/Fixtures
  - C, Other Comment: stored items, no outlets visible.

## Garage

- 94. Roof Structure & Covering
  - C, Other Comment: C, snow covered, could not evaluate.
- 95. Wall Structure & Covering
  - B, Weathered/damaged siding trim.
  - B, Siding lacks clearance to grade.
  - B, Garage is not plumb/level.
  - B, Below Minimum Requirements: B, window glass missing.
  - C, Other Comment: C, garage is full of stored items, very limited views.
- 96. Garage Doors
  - B, Weathered/deteriorated overhead door(s).
- 97. Automatic Garage Door Opener
  - NA, Not Applicable/Does Not Apply
- 98. Electrical Outlets/Fixtures
  - C, Other Comment: C, no power to garage

#### Miscellaneous

99. Clutter/Sanitation/Vermin

NA, Not Applicable/Does Not Apply

100. Other

NA, Not Applicable/Does Not Apply

#### Unit 2

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 10 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

M :=Meets Minimum Requirements C :=Comments NA :=Not Applicable/Does Not Apply B :=Below Minimum Requirements SC :=Suggested Correction

RRE:=Repair/Replace, Evaluator Verification

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

## Basement (412 5th Ave SE)

- 1. Basement Stairs/Railings
  - B, Tread depth is less than 9".
  - B, Openings in guardrail over 9".
  - B, Door opens over the staircase.
  - B, Below Minimum Requirements: B, Lower portion of stairs lack a handrail.
  - SC, Suggested Correction: SC, loose treads, cracked treads.
- 2. Basement Floors
  - C, Limited view due to stored items or furnishings.
  - B, Below Minimum Requirements: B, Cracks in floor, hollow areas.
  - C, Other Comment: C, Floor is uneven in areas, damaged areas.
- 3. Foundation Walls
  - B, Spalling in areas.
- 4. Evidence of Dampness or Staining
  - C, Evidence of past dampness and/or staining.
  - C, Efflorescence on walls.
- 5. First Floor, Floor System
  - M, Meets Minimum Requirements
- 6. Columns & Beams
  - M, Meets Minimum Requirements
- 7. Basement Sleeping Rooms
  - C, There are no basement bedrooms.
- 8. Basement Plumbing Fixtures
  - M, Meets Minimum Requirements
- 9. Sump Pumps
  - C, No sump pump present.
- 10. Smoke Detectors / CO Detectors
  - M, Meets Minimum Requirements
- 11. Basement Electrical Outlets/Fixtures
  - M, Meets Minimum Requirements

#### **Electric**

Amps:100

Volts:115/230

12. Electrical service installation

M, Meets Minimum Requirements

13. Separate 20-amp Kitchen Circuit indexed at Service Panel

M, Meets Minimum Requirements

14. Separate 20-amp Laundry Circuit indexed at Service Panel

M, Meets Minimum Requirements

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 11 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

## **Plumbing**

15. Floor Drains

C, Other Comment: - C, no floor drain visible.

16. Drain, Waste & Vent Piping

M, Meets Minimum Requirements

17. Water Supply Piping

M, Meets Minimum Requirements

18. Gas Piping

M, Meets Minimum Requirements

19. Copper Water Line Visible on the Street Side of Water Meter

M, Meets Minimum Requirements

#### Water heater

20. Water Heater & Installation

RRP, Repair/Replace: - RRP, improper flex gas line, permit required to replace.

21. Water Heater Venting

M, Meets Minimum Requirements

## Heating (412 5th Side)

HeatingFuel:Gas

HeatingType:boiler

Heating Plant Viewed in Operation

M, Meets Minimum Requirements

23. Heating Plant & Installation

LIC, Excessive scale. Safety check by licensed Mpls heating contractor required. Some repairs may require a mechanical permit.

LIC, Excessive rust on draft hood. Safety check by licensed Mpls heating contractor required. Some repairs may require a mechanical permit.

24. Heating Plant Combustion Venting

RRP, Rust holes/open joint(s). Installation of new venting requires a mechanical permit by licensed Minneapolis contractor.

25. Incinerator / Abandoned Oil Tanks / Misc Gas Fixtures

NA, Not Applicable/Does Not Apply

Evaluator Name: Alan Copia Evaluation Date: 11/17/2014 Page 12 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

## Laundry

26. Gas Piping

M, Meets Minimum Requirements

27. Dryer Venting

SC, Suggested Correction: - SC, loose connections at ductwork.

28. Plumbing Fixtures

C, Other Comment: - C, no venting visible at laundry tub.

#### Kitchen

29. Walls and Ceiling Components

M, Meets Minimum Requirements

30. Evidence of Dampness or Staining

M, Meets Minimum Requirements

31. Floor Condition

C, Floor out of level.

32. Window Size & Openable Area

M, Meets Minimum Requirements

33. Window & Door Condition/Mechanical Venting

M, Meets Minimum Requirements

34. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

35. Plumbing Fixtures

M, Meets Minimum Requirements

36. Water Flow

M, Meets Minimum Requirements

37. Gas Piping

C, Gas piping not visible.

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 13 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification
Required

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

## **Dining Room/Living Room**

38. Walls and Ceiling Components

M, Meets Minimum Requirements

39. Evidence of Dampness or Staining

M, Meets Minimum Requirements

40. Floor Area & Ceiling Height

M, Meets Minimum Requirements

41. Floor Condition

M, Meets Minimum Requirements

42. Window Size & Openable Area

M, Meets Minimum Requirements

43. Window & Door Condition

M, Meets Minimum Requirements

44. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

### Bathroom (2nd fl)

45. Walls & Ceiling Components

M, Meets Minimum Requirements

46. Evidence of Dampness or Staining

M, Meets Minimum Requirements

47. Floor Condition

M, Meets Minimum Requirements

48. Window Size & Openable Area/Mechanical Vent

M, Meets Minimum Requirements

49. Window & Door Condition

M, Meets Minimum Requirements

50. Electrical Outlets & Fixtures

M, Meets Minimum Requirements

51. Plumbing Fixtures

B, Below Minimum Requirements: - fixtures lack proper clearances.

52. Water Flow

M, Meets Minimum Requirements

**Evaluator Name**: Alan Copia **Evaluation Date**: 11/17/2014 Page 14 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification

RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

### Hallways/Stairwells

- 53. Walls and Ceiling Components
  - M, Meets Minimum Requirements
- 54. Evidence of Dampness or Staining
  - M, Meets Minimum Requirements
- 55. Floor Condition
  - M, Meets Minimum Requirements
- 56. Window & Door Condition
  - M, Meets Minimum Requirements
- 57. Electrical Outlets/Fixtures
  - M, Meets Minimum Requirements
- 58. Stairs and Railings
  - B, Below Minimum Requirements: B, Low guardrail, less than 36". B, Handrail ends do not return to wall
- 59. Smoke Detectors /CO Detectors

RRE, Repair/Replace: - RRE, A CO detector is required within 10' of each bedroom. RRE, Inoperable smoke detector at 2nd floor hallway.

## **Bedroom (2nd fl front)**

- 60. Walls and Ceiling Components
  - M, Meets Minimum Requirements
- 61. Evidence of Dampness or Staining
  - M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height
  - M, Meets Minimum Requirements
- 63. Floor Condition
  - M, Meets Minimum Requirements
- 64. Window Size & Openable Area
  - M, Meets Minimum Requirements
- 65. Window & Door Condition
  - M, Meets Minimum Requirements
- 66. Electrical Outlets/Fixtures
  - C, Limited view due to stored items.

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 15 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

## Bedroom (2nd fl mid)

60. Walls and Ceiling Components

M, Meets Minimum Requirements

61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

63. Floor Condition

M, Meets Minimum Requirements

64. Window Size & Openable Area

M, Meets Minimum Requirements

65. Window & Door Condition

M, Meets Minimum Requirements

66. Electrical Outlets/Fixtures

C. Limited view due to stored items.

### Bedroom (2nd fl rear)

60. Walls and Ceiling Components

M, Meets Minimum Requirements

61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

63. Floor Condition

M, Meets Minimum Requirements

64. Window Size & Openable Area

M, Meets Minimum Requirements

65. Window & Door Condition

M, Meets Minimum Requirements

66. Electrical Outlets/Fixtures

C, Limited view due to stored items.

#### Porch/Sunroom/Other

Not Applicable

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 16 of 19

Address: 410 5TH AVE SE Minneapolis, MN



**EVALUATION CODES:** 

RRE:=Repair/Replace, Evaluator Verification RRP:=Repair/Replace, Permit/City Inspector Required

LIC:=Safety Check, Licensed Contractor Required

Required

## Attic Space

InsulationType: Not Visible

InsulationDepth: 3-6

72. Roof Boards & Rafters / Ventilation

RRE, Repair/Replace: - RRE, Access is blocked, could not view

73. Evidence of Dampness or Staining

M, Meets Minimum Requirements

74. Electrical Outlets & Fixtures

M, Meets Minimum Requirements

75. Mechanical Venting

NA, Not Applicable/Does Not Apply

#### **Exterior**

Not Applicable

## **Open/Unheated Porch**

Not Applicable

#### Garage

Not Applicable

#### Miscellaneous

99. Clutter/Sanitation/Vermin

NA, Not Applicable/Does Not Apply

100. Other

NA, Not Applicable/Does Not Apply

**Evaluator Name:** Alan Copia **Evaluation Date:** 11/17/2014 Page 17 of 19

Address: 410 5TH AVE SE Minneapolis, MN



## **Truth in Housing Repair Notification**

City of Minneapolis-Inspections Division
Truth in Sale of Housing, 250 South 4th Street, Room 300
Minneapolis, MN 55415

**Issued To:** 11/17/2014

Irving Properties Inc 410 5TH AVE SE Minneapolis, MN 55414

Owner does not have to complete repairs if the house is not sold.

Pursuant to Minneapolis Code of Ordinances, Sections 248.20 and 248.225, the owner may make the repairs. If the owner makes the repairs, a Certificate of Approval (needed for closing) will be issued after the repairs have been inspected and approved. The owner does not have to complete the repairs if the house does not sell. If the owner does not make the repairs, the buyer must sign an acknowledgement of responsibility form (provided by the City) and return it to the City. The buyer has 90 days from closing to complete the repairs. Your prompt cooperation in attending to the repair items is appreciated however, failure to comply by these deadlines may result in legal action.

#### **REQUIRED REPAIRS**

ID	Description	Area	Comment
12	Electrical service installation	1 - Electric	Electric shock possible by direct contact, missing breaker in panel Multiple breakers missing
72	Roof Boards & Rafters / Ventilation	1 - Attic Space	Repair/Replace: - RRE, access to attic is locked, could not view
59	Smoke Detectors /CO Detectors	2 - Hallways/Stairwells	Repair/Replace: - RRE, A CO detector is required within 10' of each bedroom. RRE, Inoperable smoke detector at 2nd floor hallway.
72	Roof Boards & Rafters / Ventilation	2 - Attic Space	Repair/Replace: - RRE, Access is blocked, could not view

#### **SAFETY CHECKS**

The systems listed below must be checked by a licensed contractor. The contractor must be licensed by the City of Minneapolis and/or the State of Minnesota in that specific trade to check the work. Return safety check forms to the address above or fax to (612) 673-2437. If "Evaluator Return" is indicated below, the evaluator may return to view he system that was not in operation at the time of the initial evaluation. The evaluator may find additional work is needed on the system.

If the system was repaired or replaced, only a licensed contractor (not the evaluator) can do the safety check. Permits may be needed.

ID	Description	Area	Comment
23	Heating Plant & Installation	2 - Heating(412 5th Side)	Excessive scale. Safety check by licensed Mpls heating contractor required. Some repairs may require a mechanical permit.
23	Heating Plant & Installation	2 - Heating(412 5th Side)	Excessive rust on draft hood. Safety check by licensed Mpls heating contractor required. Some repairs may require a mechanical permit.

#### **PERMIT REQUIRED REPAIR**

The permit must be pulled before scheduling. Call the inspector listed on the permit to set an appointment. You need to have the permit number to set the appointment. There will be a charge for the permit, which covers the inspection.

Comment
Missing or improper double check valve with
intermediate atmospheric vent (DCVIAV or backflow
preventer) on water supply to boiler. Plumbing permit

Evaluator Name: Alan Copia Evaluation Date: 11/17/2014 Page 18 of 19

Address: 410 5TH AVE SE Minneapolis, MN



required.

Heating Plant Combustion Venting 1 - Heating(410 5th Side) Rust holes/open joint(s). Installation of new venting

requires a mechanical permit by licensed Minneapolis

contractor

Water Heater & Installation 2 - Water heater Repair/Replace: - RRP, improper flex gas line, permit

required to replace.

24 Heating Plant Combustion Venting 2 - Heating(412 5th Side) Rust holes/open joint(s). Installation of new venting

requires a mechanical permit by licensed Minneapolis

contractor.

#### **Reinspection Process**

When all the items are completed they must be inspected and approved.

#### For items that need a permit:

If your notification indicates PERMIT NEEDED, the permit(s) must be pulled and work completed BEFORE the re-inspection takes place. If you are a homeowner occupant of a single family house, you may obtain a permit, if you are not, you must hire a licensed contractor. Bring this notification with you when you apply for permits.

#### For items that do not need a permit:

Call the evaluator who did the initial TISH report to re-inspect all the non-permit items. The evaluator's name and phone number are on the bottom of page 1 of the report. There will be a charge for this inspection.

#### **Appeal**

24

20

This repair notice may be appealed. Section 248.150 of the Minneapolis Code of Ordinances provides that an appeal must be filed in writing within thirty (30) days of the date of this notice accompanied with a \$100 filing fee. If you wish to appeal this order, call (612) 673-5840 for an application.

#### **Assistance**

If you need financial assistance to complete these repairs, you may call the Greater Metropolitan Housing Corporation (GMHC) at 612-378-7985.

Evaluator Name: Alan Copia Evaluation Date: 11/17/2014 Page 19 of 19